



TO 48. SIMILAR FOGGING OCCURS IN FRAMES 990 AND 991. HEAT SPLICES ARE POSITIONED BETWEEN FRAMES 102/103, 147/148 AND 315/316. A MANUFACTURER'S SPLICE IS PRESENT IN FRAME 1418.

D. BOTH SIDES: THE METERING IS SLIGHTLY IRREGULAR AND RANGES FROM 0.20" TO 0.55". THE TITLED FRAMES ARE NUMBERED 0000 TO 2212.

E. THERE WERE NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING ANOMALIES OTHER THAN THE ITEMS NOTED IN PARAGRAPHS B AND C.

3. POSITIVE:

A. THE PI SUITABILITY IS GOOD.

B. PRINTING AND PROCESSING ARE GOOD.

C. THE CLOUD COVER IS 20 PERCENT.

S E C R E T

--END OF MESSAGE--

1